SERE

S F C P F T 0704397 FFP S9 SITE DOTO 4000 FFP 7 OH	- 051/4
2930 1968 FEB 7 04	327 25X1
	20/(1
1. CAMERA B-18 WAS USED ON MISSION G-011 FLOWN 2 FEBRUARY	WT 64371
1968. PROCESSING WAS ACCOMPLISHED BY NAV. RECON. TECH. SUPPCEN.	VT 64274
2. ORIGINAL NEGATIVE:	
· · · · · · · · · · · · · · · · · · ·	
A. DENSITY IS GOOD THROUGHOUT THE MISSION. THERE IS A DIS	TRISUTION 7
DISTINCT DIFFERENCE IN RESOLUTION BETWEEN THE IL'S AND IR'S, CINO.	70
THE FORMER HAVING BETTER RESOLUTION OVER THE WHOLE FORMAT.	
THE RESOLUTION RANGES FROM FAIR TO GOOD.	File
	Cablo Sec.
B. 9R SIDE: A ROW OF MINUS DENSITY DOTS APPEARED IN	
ALL FORMATS 3.5 INCHES FROM THE OUTBOARD EDGE OF THE FORMAT AND	Pras
1.7 INCHES APART. FRAMES 761 AND 1369 CONTAIN MANUFACTURERS	
SPLICES; FRAME 881 CONTAINS A HEAT SPLICE. A 0.5 INCH WIDE	<u> </u>
PLUS DENSITY LINE RUNNING ACROSS THE FORMAT IS PRESENT IN FRAME	Security
41. AN 0.1 INCH WIDE AREA OF FOG EXTENDS ACROSS FRAME 1371 AT	1805G
THE MIDDLE OF THE FRAME. THE 0.5 INCH MARGIN (OUTBOARD EDGE)	
OF FRAMES 1076 THROUGH 1079 ARE EXTENSIVELY FOGGED.	
C. 9L SIDE: MINUS DENSITY DOTS ARE PRESENT IN ALL FORMATS.	F303
ATTUNIOU TUTY ADDEAD TO DE BANDON ACROCO THE PORMATE THEY ARE	
ALTHOUGH THEY APPEAR TO BE RANDOM ACROSS THE FORMAT, THEY ARE	183
EQUALLY SPACED ALONG THE MAJOR AXIS OF THE FILM. WAVERING PLUS	_
DENSITY LINES ARE PRESENT INTERMITTENTLY THROUGHOUT THE MISSION.	- INS
FRAME 002 CONTAINS A FOG STREAK EXTENDING 8.0 INCHES ACROSS	
THE FORMAT (6.0 INCHES FROM THE DATA BLOCK END OF FORMAT). A	1311131.n-4
PLUS DENSITY STREAK IS PRESENT ACROSS FRAME 910 (2.5 INCHES	SPACE
PROM TUE NAM DATA DI AGU PIN OF PARMATA APROPATMATI V TUE LAGE	25X1
FROM THE NON-DATA BLOCK END OF FORMAT). APPROXIMATELY THE LAST	1 DIA-SIV 1
489 FRAMES CONTAIN SEVERAL STRAIGHT PLUS DENSITY LINES ALONG THE	
MAJOR AXIS OF THE FILM. A MINOR EMULSION DEFECT IS PRESENT 4.0	
INCHES FROM THE INBOARD EDGE AND 6.0 INCHES FROM THE DATA BLOCK	
END OF FRAME 1407. FRAMES 910 AND 911 CONTAIN HANDLING MARKS.	Advance Copy
FAINT IMAGES OF POSITION INDICATORS ARE PRESENT IN THE DATA BLOCK	Sanifized
	With Text
IN ADDITION TO THE PROPERLY EXPOSED INDICATOR. FRAME 94 CONTAINS	
A MANUFACTURERS SPLICE; FRAME 911 CONTAINS A HEAT SPLICE.	6
D. BOTH SIDES: FRAMES 509, 915, AND 1524 APPEAR SMEARED	
DUE TO VEHICLE MANEUVERING. A MINOR AREA OF FOG LOCATED NEAR	
THE VERTICAL INDICATOR DOT IS PRESENT IN ALL FORMATS. EDGE STATIC	
AND ROLLER CHATTER ARE PRESENT ALONG BOTH EDGES OF BOTH SIDES.	13
FRAME 1682 IS A 3R. MODE 5 WAS USED THROUGHOUT. THE LAST TITLED	
FRAME IS 1684. THE COUNTER SKIPPED FRAME NUMBER 1682.	are the second of the
3. POSITIVES:	
A. PRINTING AND PROCESSING WERE GOOD.	
B. P.I. SUITABILITY IS FAIR TO GOOD DUE TO VARIABILITY	
IN RESOLUTION.	
C. CLOUDS OBSCURE APPROXIMATELY 30 PERCENT OF THE MISSION.	=
SECRET	
그 사람들은 경기를 받는 것이 되었다. 그는 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은	

END OF MESSAGE